



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
August 18, 2009

Reviewed: Z/A

<b>Mine Name:</b> Wah Wah Mine	<b>Permit Number:</b> S/021/0031
<b>Operator Name:</b> Jimmy Hodges	<b>Inspection Date:</b> 07/01/2009
<b>Inspector(s):</b> Brett Gregory for Tom Munson <u>T</u>	<b>Time:</b> 4:00 pm
<b>Other Participants:</b> None	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**Bond Amount:** \$6,000.

**Permit fee:** Current.

**Purpose of Inspection:** This was a routine inspection to photograph and document the site conditions.

**Inspection Summary:** (photos attached).

2) There are abandoned tires on site that need to be removed.

12) I gathered GPS data for the amount of disturbance. The total disturbance of this mine is 0.60 acres.

**Conclusions and Recommendations:** The amount of mining performed is small and doesn't pose any environmental concern. DOGM will continue to monitor the progress of this mining operation.

**Inspector's Signature**

BG:tm:vs

cc: Jimmy Hodges

ed\_ginouves@blm.gov

O:\M021-Iron\S0210031-WahWah\inspections\insp-07012009.doc



Access gate installed.



Tires found on the premises.



View of disturbance.



Secondary view.





Protective tool cover.



Drill and blasting possibly performed.



Pit.



Overburden waste rock.